



**Megapress-Adaptor**  
cu SC-Contur, model 4211



**Megapress-Adaptor**  
cu SC-Contur, model 4211



$\frac{3}{8}$  (17,2) x R  $\frac{3}{8}$



**Megapress-Adaptor**  
cu SC-Contur, model 4211

**740 177**



$\frac{3}{8}$  (17,2) x R  $\frac{1}{2}$



**Megapress-Adaptor**  
cu SC-Contur, model 4211

**740 160**



$\frac{1}{2}$  (21,3) x R  $\frac{1}{2}$



**Megapress-Adaptor**  
cu SC-Contur, model 4211

**695 279**



$\frac{3}{4}$  (26,9) x R  $\frac{3}{4}$



**Megapress-Adaptor**  
cu SC-Contur, model 4211

**695 286**



1 (33,7) x R 1



**Megapress-Adaptor**  
cu SC-Contur, model 4211

**695 293**



1 $\frac{1}{4}$  (42,4) x R 1 $\frac{1}{4}$



**Megapress-Adaptor**  
cu SC-Contur, model 4211

**695 309**



1 $\frac{1}{2}$  (48,3) x R 1 $\frac{1}{2}$

**695 316**

2 (60,3) x R 2

**695 323**